

Firmware Update VSX-LX103 and VSX-933 (01-14-2021)

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

This update may be installed via USB or Network.

**VSX-LX103, VSX-933
(Current Version 1071-2000-1070-0011)**

The 01/14/2021 update will address the following:

1. Change login method of TIDAL for enhancing security.*
*Please refer to the link below for more details.
https://www.onkyo.com/manual/sup/upd/tidal_onk.pdf
2. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
3. Improve reception capability in certain TuneIn Radio stations.
4. Minor bug fixes and improvements stability.

Previous Updates:

The 09/23/2020 update will address the following and includes previous updates:

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
4. Improve the stability of operation when returning from Network Standby.

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
*Service of Amazon Music may vary by country.
2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.

Version 1050-9000-1060-0011

- Update Chromecast built-in version to 1.36.
- Improve search performance of music server.
- Improve playback stability for FLAC files.

Version 1040-8000-1050-0010

- Improve playback stability for Chromecast Built-in.
- Improve playback stability for Airplay.
- Improve the playability for certain WAV files.

Version 1040-7000-1050-0010

- Support AirPlay2.
- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.
- https://jp.pioneer-audiovisual.com/manual/sup/upd/hdmi_4k_pio.pdf (For VSX-LX103 only)
- http://jp.pioneer-audiovisual.com/manual/vsx933/supple_933.pdf (For VSX-933 only)
- Minor bug fixes and improvements stability.

Version 1030-6000-1040-0010

- Minor bug fixes and improvements stability.

Version 1030-5000-1040-0010

- Adds support for Amazon Music.
Amazon Music service requires that you have Amazon Prime account or Amazon Music Unlimited account
Pioneer Remote App is required for initial set-up of Amazon Music.
For detail about updated function, please refer to the link below.
http://jp.pioneer-audiovisual.com/manual/sup/upd/amazon_pio.pdf -
Adds setting of Preset Volume for Sonos Connect.
For detail about updated function, please refer to the link below. http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf -
Enhanced security.
Depending on the Firmware version, update will be needed 2 times.
- Minor bug fixes and improvements stability.

Version 1020-4000-0030-0010

- Enhanced security.
- Adds support for Deezer HiFi.
- Depending on the Firmware version, update will be needed 2 times.

- Minor bug fixes and improvements stability.

Version 1010-3000-0030-0010

- Adds support for Sonos Connect.

For detail about updated function, please refer to the link below.

http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf

- Minor bug fixes and improvements stability.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.