

## **Firmware Update VSX-LX303 and VSX-LX503 (01-14-2021)**

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

**This update may be installed via USB or Network.**

**VSX-LX303, VSX-LX503  
(Current Version 1091-2000-1070-0011)**

**The 01/14/2021 update will address the following:**

1. Change login method of TIDAL for enhancing security.\*  
\*Please refer to the link below for more details.  
[https://www.onkyo.com/manual/sup/upd/tidal\\_onk.pdf](https://www.onkyo.com/manual/sup/upd/tidal_onk.pdf)
2. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
3. Improve reception capability in certain TuneIn Radio stations.
4. Minor bug fixes and improvements stability.

### **Previous Updates:**

**The 09/23/2020 update will address the following and includes previous updates:**

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
4. Improve the stability of operation when returning from Network Standby.

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.  
\*Service of Amazon Music may vary by country.
2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.

Version 1070-9000-1060-0011

- Update Chromecast built-in version to 1.36.
- Improve search performance of music server.

- Improve playback stability for FLAC files.

Version 1060-8000-1050-0010

- Improve playback stability for Chromecast Built-in.
- Improve playback stability for Airplay.
- Improve the playability for certain WAV files.

Version 1060-7000-1050-0010

- Support AirPlay2.
- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.
- [https://jp.pioneer-audiovisual.com/manual/sup/upd/hdmi\\_4k\\_pio.pdf](https://jp.pioneer-audiovisual.com/manual/sup/upd/hdmi_4k_pio.pdf)
- Minor bug fixes and improvements stability.

Version 1050-6000-1040-0010

- Minor bug fixes and improvements stability.

Version 1040-5000-1040-0010

- Adds support for Amazon Music.

Amazon Music service requires that you have Amazon Prime account or Amazon Music Unlimited account

Pioneer Remote App is required for initial set-up of Amazon Music.

For detail about updated function, please refer to the link below.

[http://jp.pioneer-audiovisual.com/manual/sup/upd/amazon\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/amazon_pio.pdf) - (VSX-LX503) Adds support for eARC.

HDMI cable needs to be Ethernet-enabled HDMI cable.

For detail about updated function, please refer to the link below.

[http://jp.pioneer-audiovisual.com/manual/sup/upd/earc\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/earc_pio.pdf)

- Adds setting of Preset Volume for Sonos Connect.

For detail about updated function, please refer to the link below. [http://jp.pioneer-](http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf)

[audiovisual.com/manual/sup/upd/sonosconnect\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf) - Enhanced security.

Depending on the Firmware version, update will be needed 2 times.

- Minor bug fixes and improvements stability.

Version 1030-4000-0030-0010

- Enhanced security.
- Adds support for Deezer HiFi.
- Depending on the Firmware version, update will be needed 2 times.

Version 1020-3000-0030-0010

- Adds support for Sonos Connect.

For detail about updated function, please refer to the link below.

[http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect\\_pio.pdf](http://jp.pioneer-audiovisual.com/manual/sup/upd/sonosconnect_pio.pdf)

- Minor bug fixes and improvements stability.

## **Firmware Update Instructions**

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.