Firmware Update Pioneer SC-LX701/801/901 (01-14-2021)

We are pleased to offer this firmware update for the best possible performance of your Pioneer AV Receiver.

This update may be installed via USB or Network. SC-LX701/801/901 (Current Version 2190-5000-5080-0011)

The 01/14/2021 update will address the following:

- 1. Change login method of TIDAL for enhancing security.*
- *Please refer to the link below for more details.

https://jp.pioneer-audiovisual.com/manual/sup/upd/tidal_pio.pdf

- 2. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
- 3. Improve reception capability in certain TuneIn Radio stations.
- 4. Minor bug fixes and improvements stability.

Previous Updates:

The 09/23/2020 update will address the following and includes previous updates:

- 1. Improve reception capability in certain TuneIn Radio stations.
- 2. Fix the issue of Bluetooth connection with certain devices.
- 3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
- 4. Improve the stability of operation when returning from Network Standby.

The 02/06/2020 update will address the following and includes previous updates:

- 1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
- *Service of Amazon Music may vary by country.
- 2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.

The 11/14/2019 update will address the following and includes previous updates:

- 1. Update Chromecast built-in version to 1.36.
- 2. Improve search performance of music server.
- 3. Improve playback stability for FLAC files.

The 7/4/2019 update will address the following and includes previous updates:

- 1. Improve playback stability for Chromecast Built-in.
- 2. Improve the playability for certain WAV files.

Firmware Update Instructions:

Update the firmware via network or USB connection. "Updating the firmware via network" You can update the firmware by connecting the unit to a network. "Updating the firmware via USB connection" You need a 128 MB or larger capacity USB storage for updating. For details, see "Firmware Update" of the Instruction Manual.