

Firmware Update VSX-LX302 (01-14-2021)

We are pleased to offer this firmware update for the best possible performance of your AV Receiver.

This update may be installed via USB or Network.

VSX-LX302 (Current Version **1131-8020-3070-0011)**

The 01/14/2021 update will address the following:

1. Change login method of TIDAL for enhancing security.*
*Please refer to the link below for more details.
https://www.onkyo.com/manual/sup/upd/tidal_onk.pdf
2. Fix the issue that cannot display the logo of certain TuneIn Radio stations.
3. Improve reception capability in certain TuneIn Radio stations.
4. Minor bug fixes and improvements stability.

Previous Updates:

The 09/23/2020 update will address the following and includes previous updates:

1. Improve reception capability in certain TuneIn Radio stations.
2. Fix the issue of Bluetooth connection with certain devices.
3. Fix the issue that start tuning operation when pressing UP/DOWN cursor at TUNER selector.
4. Improve the stability of operation when returning from Network Standby.

The 02/06/2020 update will address the following and includes previous updates:

1. Improve the list viewing for "Albums/ Artists/ Songs" in My Music of Amazon Music.
*Service of Amazon Music may vary by country.
2. Correct "the unstable elapsed time" and "no album art" when playback through Music Server or USB.

- Improve search performance of music server.
- Improve playback stability for FLAC files.

Version 1101-4020-3060-0010

- Improve playback stability for Chromecast Built-in.

- Improve playback stability for Airplay.
- Improve the playability for certain WAV files.

Version 1101-3020-3060-0010

- Add setting to switch "Standard" and "Enhanced" according to HDMI 4K signal format.

http://jp.pioneer-audiovisual.com/manual/vsx933/supple_933.pdf -
Minor bug fixes and improvements stability.

Version 1091-2020-3050-0010

- Minor bug fixes and improvements stability.

Version 1081-1020-3050-0010

- Adds support for Amazon Music.

Amazon Music service requires that you have Amazon Prime account or Amazon Music Unlimited account

Pioneer Remote App is required for initial set-up of Amazon Music.

For detail about updated function, please refer to the link below.

http://jp.pioneer-audiovisual.com/manual/sup/upd/amazon_pio.pdf -
Enhanced security.

Depending on the Firmware version, update will be needed 2 times.

- Minor bug fixes and improvements stability.

Version 1071-0020-2050-0010

- Enhanced security.

- Adds support for Deezer HiFi.

Version 1060-9020-2050-0010

- Improvement of audio output when playback certain Dolby Digital Plus contents.

- Minor bug fixes and improvements stability.

Version 1050-8010-2040-0008

- Improve the noise during playback via USB/Network

Version 1050-7010-2040-0008

- Adds support of external audio inputs* for "FlareConnect".

*For detail about external audio inputs, please refer to the link below.

<http://pioneer-audiovisual.com/flareconnect/> - Minor bug fixes and improvements stability.

Version 1040-5010-2030-0008

- Adds support for new multi-room audio playback function "FlareConnect".

*All audio devices in group and "Pioneer Remote" App is required to update to the latest version.

How to Enjoy FlareConnect

<http://intl.pioneer-audiovisual.com/letthemusicplay/setup>

Introduction of multi-room audio functions

?<http://intl.pioneer-audiovisual.com/letthemusicplay/>

- Improvement for pass-through function of Dolby Vision signal.
- Minor bug fixes and improvements stability.

Version 1040-4010-0030-0008

- Adds support for DTS Play-Fi.

*To use Play-Fi, you need to download the application.

http://jp.pioneer-audiovisual.com/manual/sup/upd/playfi_pio.pdf

Before starting to use Play-Fi, set "On" at the "Network Standby" ("NET Stby") setting.

The unit will automatically power on and change the selector to "NET" or "Network".

- Expand playable content of DTS:X.
- Adds "Play Queue" function.

For detail about updated function, please refer to the link below.

http://jp.pioneer-audiovisual.com/manual/sup/upd/queue_pio.pdf

- Adds "Search/ Sort" function on Music server.
- Adds "Display WAV file information (album art, artist, album) via USB" function.

Please note that only above functions are added this time. Please refer to the link below and find out the explanation of your related function.

http://jp.pioneer-audiovisual.com/manual/sup/upd/audio1709_na_pio.pdf

Important notice: * The fore mentioned functions depend on model - not all functions are available for each model.

- Minor bug fixes and performance improvements.

Version 1010-2000-0000-0008

- Adds support for Chromecast built-in.

*Chromecast-enabled applications is required to enjoy Chromecast built-in.

*As an initial setting, before starting to use Chromecast built-in, you need to accept the PRIVACY POLICY on our smartphone application "Pioneer Remote App".

For more detailed information, Please refer to below. http://jp.pioneer-audiovisual.com/manual/sup/upd/chromecast_pio.pdf

- Minor bug fixes and performance improvements.

Firmware Update Instructions

Update the firmware via network or USB connection.

"Updating the firmware via network"

You can update the firmware by connecting the unit to a network.

"Updating the firmware via USB connection"

You need a 128 MB or larger capacity USB storage for updating.

For details, see "Firmware Update" of the Instruction Manual.